PATENT

00684.003316

NOV 0 4 2005

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
	: Examiner: Sophia S. Chen
AKIHIKO TAKEUCHI ET AL.)
	: Group Art Unit: 2852
Appl. No.: 10/057,969)
	: Confirmation No.: 2472
Filed: January 29, 2002	Certificate
·	•
For: IMAGE HEATING APPARATUS HAVING	G) NOV 1 0 2005
A LIMITING MEMBER	
	of Correction
U.S. Patent No.: 6,937,837 B2	:
)
Issued: August 30, 2005	· November 4 2005

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee

for such Certificate of Correction.

11/07/2005 CNGUYEN 00000096 6937837

01 FC:1811

100.00 OP

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

Lawrence A. Stahl Attorney for Patentees Registration No. 30,110

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

LAS:eyw

Stable Here Ould Name of Stable PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,937,837 B2

DATED

August 30, 2005

INVENTOR(S) :

AKIHIKO TAKEUCHI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 8, "employs" should read --employ--.

COLUMN 3:

Line 38, "th" should read --the--.

COLUMN 7:

Line 56, "prints" should read --print--.

COLUMN 15:

Line 57, "polyimde" should read --polyimide--.

COLUMN 17:

Line 11, " Δt (=bxa)" should read -- Δt (=b-a)--.

COLUMN 18:

Line 9, "flange" should read --flanges--.

COLUMN 22:

Line 40, "of" should read --for--.

COLUMN 23:

Line 55, "<miscellanies>" should read --<miscellaneous>--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. <u>6,937,837 B2</u>

No. of add'l. copies @ 30¢ per page

➡ _

Form PTO 1050 (Rev. 3-82) (Form#30)

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,937,837 B2

DATED

August 30, 2005

INVENTOR(S) :

AKIHIKO TAKEUCHI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 24:

Line 24, "portion" should be deleted.

COLUMN 26:

Line 19, "of coil" should read --a coil--. Line 20, "layers," should read --layer,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

PATENT NO. <u>6,937,837 B2</u>

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82) (Form#30)

NOV 1 6 2005

Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,937,837 B2

DATED

August 30, 2005

INVENTOR(S) :

AKIHIKO TAKEUCHI ET AL.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2:

Line 8, "employs" should read --employ--.

COLUMN 3:

Line 38, "th" should read --the--.

COLUMN 7:

Line 56, "prints" should read --print--.

COLUMN 15:

Line 57, "polyimde" should read --polyimide--.

COLUMN 17:

Line 11, " Δt (=bxa)" should read -- Δt (=b-a)--.

COLUMN 18:

Line 9, "flange" should read -- flanges--.

COLUMN 22:

Line 40, "of" should read --for--.

COLUMN 23:

Line 55, "<miscellanies>" should read --<miscellaneous>--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO

30 Rockefeller Plaza

New York, New York 10112-3801

(212) 218-2100 - Telephone

(212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82) (Form#30)

PATENT NO. 6,937,837 B2

No. of add'l. copies @ 30¢ per page



PRINTER'S TRIM LINE Staple Here Only!

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,937,837 B2

DATED

August 30, 2005

INVENTOR(S) :

AKIHIKO TAKEUCHI ET AL.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 24:

Line 24, "portion" should be deleted.

COLUMN 26:

Line 19, "of coil" should read --a coil--. Line 20, "layers," should read --layer,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

Form PTO 1050 (Rev. 3-82)

(Form#30)

PATENT NO. 6,937,837 B2

No. of add'l. copies @ 30¢ per page



NOV 1 6 2000